

CLEVELAND AVENUE & MYRTLE AVENUE SAFETY IMPROVEMENTS



THIS PROJECT WILL PROTECT
SMALL BUSINESS OWNERS FROM
DAMAGE AND RISK TO THEIR
PATRONS AND BUSINESSES.

 envdesigngroup.com

Impact

This project corrected a long standing safety problem and will protect adjacent small business owners from continual damage and risk to their patrons and businesses.

Project Description

Environmental Design Group was hired to implement safety improvements at this unusual intersection. The intersection is in the middle of a curve in Cleveland Avenue where northbound drivers often depart the road and crash into adjacent store fronts on the northeast corner. The project was to restripe the 4 Cleveland Avenue lanes to lessen the curve, replace the existing traffic signal, improve the curb ramp and cross walk locations, and on the northeast corner add a bump out with new northbound curb alignment. Extensive utility coordination between private and city utilities was required to install the new mast arm traffic signal poles and drainage upgrades.